


Saving on material cost


By saving of weight



Using cold formed sections, means achieving an important saving of steel weight, sa shown in the following graphs.

WEIGHT SAVING CEE PROFILE VS. IPE/HEA PROFILE

Moment of inertia Ix [cm4]



WEIGHT SAVING I SIGMA PROFILE VS. IPE/HEA PROFILE

Moment of inertia Ix [cm4]

